



Request for Quote

STATE OF RHODE ISLAND AND PROVIDENCE PLANTATIONS
 CAPITOL HILL
 PROVIDENCE RI 02908

CREATION DATE : 29-NOV-06
BID NUMBER: 7002783
TITLE: JOHN DEERE 410E BACKHOE
 BUCKET/COUPLER REPLACEMENT

BID CLOSING DATE AND TIME:
 19-DEC-2006 11:30:00

BUYER: Hill, Lisa
PHONE #: 401-222-2142

**B
I
L
L
T
O**
DOT MAINTENANCE DIVISION
MAIN OFFICE
360 LINCOLN AVE
WARWICK, RI 02888
US

**S
H
I
P
T
O**
DOT MAINTENANCE BUSINESS OFFICE
360 LINCOLN AVE
WARWICK, RI 02888
US

Requisition Number:

Line	Description	Quantity	Unit	Unit Price	Total
	PRICING MUST BE INCLUSIVE OF ALL FREIGHT. DELIVERY _____ CONTACT PERSON: CHARLES OBREITER 401-222-6815				
1	DOT; MAINT - WAIN ROY SWINGER COUPLER	1	Each		
2	DOT; MAINT - 24" HD WAIN ROY BUCKET	1	Each		
3	DOT; MAINT - WHIP HOSES	1	Each		
4	DOT; MAINT - LABOR TO REMOVE THUMB AND TO INSTALL SWINGER COUPLER, BUCKET AND ADJUST PRESSURES. VENDOR WILL LEAVE UPPER MOUNT ON STICK IN CASE THUMB NEEDS TO BE RETROFITTED IN THE FUTURE.	1	Each		

It is the Vendor's responsibility to check and download any and all addenda from the RIVIP. This offer may not be considered unless a signed RIVIP generated Bidder Certification Cover Form is attached and the Unit Price column is completed. The signed Certification Cover Form must be attached to the front of the offer

Contract Terms and Conditions

Table of Contents

Terms and Conditions.....	II
BID STANDARD TERMS AND CONDITIONS	II
TERMS AND CONDITIONS FOR THIS BID	II
RIVIP INFO - BID SUBMISSION REQUIREMENTS	II

Terms and Conditions

BID STANDARD TERMS AND CONDITIONS

TERMS AND CONDITIONS FOR THIS BID

RIVIP INFO - BID SUBMISSION REQUIREMENTS

It is the Vendor's responsibility to check and download any and all addenda from the RIVIP. This offer may not be considered unless a signed RIVIP generated Bidder Certification Cover Form is attached and the Unit Price column is completed. The signed Certification Cover Form must be attached to the front of the offer. When delivering offers in person to One Capitol Hill, vendors are advised to allow at least one hour additional time for clearance through security checkpoints.