



Request for Quote

STATE OF RHODE ISLAND AND PROVIDENCE PLANTATIONS
 ONE CAPITOL HILL
 PROVIDENCE RI 02908

CREATION DATE : 16-APR-13
BID NUMBER: 7461343,1
TITLE: Repair and Modifications to Walkway, DLT

BID CLOSING DATE AND TIME: 26-APR-2013 11:30:00

BUYER: Ohara 2nd, John F
PHONE #: 401-574-8125

B
I
L
L
T
O
 DOA CONTROLLER
 ONE CAPITOL HILL, 4TH FLOOR
 SMITH ST
 PROVIDENCE, RI 02908
 US

S
H
I
P
T
O
 DLT BUSINESS AFFAIRS UNIT
 BUILDING #73
 1511 PONTIAC AVE
 CRANSTON, RI 02920
 US

Requisition Number: 1307902
Amendment Description: Addendum Number One

Line	Description	Quantity	Unit	Unit Price	Total
1	<p>Questions concerning this solicitation must be received by the Division of Purchases at: construction@purchasing.ri.gov no later than April 12, 2013 at 12:00 Noon (ET). Questions should be submitted in a Microsoft Word attachment. Please reference the RFQ# 7461343 on all correspondence. Questions received, if any, will be posted on the Internet as an addendum to this solicitation. It is the responsibility of all interested parties to download this information. Addendum Number One</p> <p>Per the issuance of this ADDENDUM #1 (5 pages, including the cover sheet) the following change(s) are noted:</p> <p>Please be advised the Bid Closing Date and Time has been extended: From: 4/19/13 at 11:30 AM To: 4/26/13 at 11:30 AM</p> <p>TOTAL COST FOR REPAIR AND MODIFICATION TO WALKWAY AT DLT BLDG 73 PONTIAC AVE, CRANSTON</p>	1.00	Each		

Delivery: _____

Terms of Payment: _____

It is the Vendor's responsibility to check and download any and all addenda from the RIVIP. This offer may not be considered unless a signed RIVIP generated Bidder Certification Cover Form is attached and the Unit Price column is completed. The signed Certification Cover Form must be attached to the front of the offer



STATE OF RHODE ISLAND AND PROVIDENCE PLANTATIONS

Department of Administration
DIVISION OF PURCHASES
One Capitol Hill
Providence, RI 02908-5855

Tel: (401) 574-8100
Fax: (401) 574-8387
Website: www.purchasing.ri.gov

April 16, 2013

ADDENDUM NUMBER ONE

RFQ # 7461343

TITLE: Repair and Modifications to Walkway, DLT

Closing Date and Time: 4/26/13 at 11:30 AM (Note Change)

Per the issuance of this ADDENDUM #1 (4) pages, including the cover sheet the following change(s) are noted:

Please be advised the Bid Closing Date and Time has been extended to:


From: 4/19/13 at 11:30 AM

To: 4/26/13 at 11:30 AM

Specification Change /Addition / Clarification

Attached are the questions and answers we received regarding this Request for Quote.

Also attached is a copy of the pre-bid conference sign in sheet.



STATE OF RHODE ISLAND AND PROVIDENCE PLANTATIONS

Department of Administration
DIVISION OF PURCHASES
One Capitol Hill
Providence, RI 02908-5855

Tel: (401) 574-8100
Fax: (401) 574-8387
Website: www.purchasing.ri.gov

April 16, 2013

Addendum Number One
Bid 7461314 Repair and Modifications to Walkway, DLT

Would you please clarify the following items?

On page 2 of 7

Area A

A 7 bike wave or serpentine pipe rack with black polyester coating will be supplied and installed by the contractor. What is the manufacturer and model number of the bike rack?

Answer: Suggested vendor is SiteScapes Inc.

Model not stated

Capacity, 7 bikes

Mount, embedded

Color: black powder coat over zinc epoxy

Area B

This paragraph states that the handrail will be removed, repaired if necessary and reinstalled however on page 5 of 7 the note on the drawing states to replace handrail. Are we to reinstall the existing handrail or replace with a new handrail?

Answer: Safety rail @ doors

Remove, repair and install. Contractor must provide like replacement if more cost effective.

What is the manufacturer and model number of the proposed bicycle rack?
As noted on new drawing, Wagner Companies, specifics in specification.

What is the disposition of the handrail?
Repair is acceptable; intention is to retain original integrity.

What is the proposed layout of the under drain system?
As noted on new drawing

What is the location for the existing bench?
To be determined

What is the new quantity for replacing concrete curbing?

As noted on new drawing

What is the new quantity for replacing concrete sidewalks?

As noted on new drawing

What scoring pattern is required on the concrete pad at the front door?

Scoring will consistent and similar to adjacent areas

Does the existing catch basin require the rebuilding of the top section to address the sunken area that is adjacent to it?

Yes

What provisions are required to access the front door during construction?

Access must be maintained during Business Hours. A safe, temporary walkway may be utilized.

In the turf areas adjacent to the concrete is seeding allowed in place of sod?

No

What is the paint specification for the pavement markings?

Paint for pavement marking acceptable to RIDOT

Are there any alternatives to the DTM paint finish on the proposed bollards?

Equivalent, corrosion resistant

Clarifications:

- a. Existing curbing to be removed and replaced from the outside radius section in area "C" to a full joint section after the existing storm drainage grate shown on the attached diagram.
- b. Area "D" – Remove and reinstall approximately 50 l.f. of concrete sidewalk.
- c. 4" PVC Drain Lines – Install new 4" pvc drain lines as shown on the attached diagram.
- d. Bike Rack – As manufactured by Wagner Companies or approved equal

SIGN IN SHEET

LOCATION DLT
DATE _____ TIME _____

1. Rich I CARUS CONSTRUCTION
2. Al Paulos Tower Construction AL@Towerconstructioncorp.com
3. JEFF JOAQUIN IPC JEFF@PAWUCKEASPHALT.COM
4. J.R. Wilbur Wilco Dev. JWilbur@WilcoDevelopment.com
5. L. Valverde Hartford Spring Anthony@HartfordSpring.com
6. STEVEN FERRI FERRI Const Co SRF@HOTMAIL.COM
7. James Klowan Narragansett Improvement Co. JKLOWAN@NICORRE.COM
8. Bill ANDERSON, AGENCY
9. VEE FARIA AGENCY
10. ANDY OMICIOU AGENCY
11. MARK BARNES AGENCY
12. CARLTON AMARAL AGENCY
13. _____
14. _____
15. _____
16. _____
17. _____

