



State of Rhode Island, Department of Administration  
Division of Purchases  
One Capitol Hill  
Providence, Rhode Island 02908  
[www.purchasing.ri.gov](http://www.purchasing.ri.gov) (401)574-8100

This solicitation has been awarded to the following vendor(s):

<u>Vendor Name</u>	<u>PO Number</u>
HOWARD P. FAIRFIELD LLC	3174396

Line Numb	Description	Supplier	Unit	Award Price	Quote Price (USD)
# 1	MPA-442 2/1/10-6/30/11 Cost for the purchase and installation of a plow blade with trip edge springs 7 1/2'	HOWARD P FAIRFIELD LLC	Each	3883.72	3,883.72
# 2	MPA-442 2/1/10-6/30/11 Cost for the purchase and installation of a plow blade with trip edge springs 8'	HOWARD P FAIRFIELD LLC	Each	4105.9	4,105.90
# 3	MPA-442 2/1/10-6/30/11 Cost for the purchase and installation of a plow blade with trip edge springs 9'	HOWARD P FAIRFIELD LLC	Each	4818.67	4,818.67
# 4	MPA-442 2/1/10-6/30/11 Cost for the purchase and installation of a plow blade with trip edge springs 10'	HOWARD P FAIRFIELD LLC	Each	5561.8	5,561.80
# 5	MPA-442 2/1/10-6/30/11 Additional cost for the purchase and installation of an optional curved deflector 7 1/2'	HOWARD P FAIRFIELD LLC	Each	350.5	350.5
# 6	MPA-442 2/1/10-6/30/11 Additional cost for the purchase and installation of an optional curved deflector 8'	HOWARD P FAIRFIELD LLC	Each	350.5	350.5
# 7	MPA-442 2/1/10-6/30/11 Additional cost for the purchase and installation of an optional curved deflector 9'	HOWARD P FAIRFIELD LLC	Each	423.75	423.75
# 8	MPA-442 2/1/10-6/30/11 Additional cost for the purchase and installation of an optional curved deflector 10'	HOWARD P FAIRFIELD LLC	Each	435.75	435.75
# 9	MPA-442 2/1/10-6/30/11 Cost for the purchase and installation of a trip edge spring assembly, if needed, 7 1/2'	HOWARD P FAIRFIELD LLC	Each	80	80
# 10	MPA-442 2/1/10-6/30/11 Cost for the purchase and installation of a trip edge spring assembly, if needed, 8'	HOWARD P FAIRFIELD LLC	Each	80	80
# 11	MPA-442 2/1/10-6/30/11 Cost for the purchase and installation of a trip edge spring assembly, if needed, 9'	HOWARD P FAIRFIELD LLC	Each	80	80
# 12	MPA-442 2/1/10-6/30/11 Cost for the purchase and installation of a trip edge spring assembly, if needed, 10'	HOWARD P FAIRFIELD LLC	Each	80	80
# 13	MPA-442 2/1/10-6/30/11 Cost for the purchase and installation of angle pistons, if needed, 7 1/2'	HOWARD P FAIRFIELD LLC	Each	195	195
# 14	MPA-442 2/1/10-6/30/11 Cost for the purchase and installation of angle pistons, if needed, 8'	HOWARD P FAIRFIELD LLC	Each	195	195
# 15	MPA-442 2/1/10-6/30/11 Cost for the purchase and installation of angle pistons, if needed, 9'	HOWARD P FAIRFIELD LLC	Each	230.5	230.5

# 16	MPA-442 2/1/10-6/30/11 Cost for the purchase and installation of angle pistons, if needed, 10'	HOWARD P FAIRFIELD LLC	Each	230.5	230.5
# 17	MPA-442 2/1/10-6/30/11 Cost for the purchase and installation of hoist pistons, if needed, 7 1/2'	HOWARD P FAIRFIELD LLC	Each	175.18	175.18
# 18	MPA-442 2/1/10-6/30/11 Cost for the purchase and installation of hoist pistons, if needed, 8'	HOWARD P FAIRFIELD LLC	Each	175.18	175.18
# 19	MPA-442 2/1/10-6/30/11 Cost for the purchase and installation of hoist pistons, if needed, 9'	HOWARD P FAIRFIELD LLC	Each	310.63	310.63
# 20	MPA-442 2/1/10-6/30/11 Cost for the purchase and installation of hoist pistons, if needed, 10'	HOWARD P FAIRFIELD LLC	Each	310.63	310.63
# 21	MPA-442 2/1/10-6/30/11 Provide a rate per hour for installation services not covered above	HOWARD P FAIRFIELD LLC	Hour	80	80
# 22	MPA-442 2/1/10-6/30/11 Provide a rate per hour for welding services	HOWARD P FAIRFIELD LLC	Hour	80	80