

Solicitation Information August 19<sup>th</sup>, 2019

## ADDENDUM # 1

# **RFQ# 7598904**

TITLE: Exterior and Interior Masonry Repairs at 1951 Smith St., North Providence

Submission Deadline is:

Friday August 30<sup>th</sup>, 2019 at 11:00 am (EST)

# Note to vendors:

**Attached includes:** 

- Questions received with answers. No more questions will be answered.
- Agency notes from prebid.
- Sign in sheet from non-mandatory prebid held on August 14<sup>th</sup>, 2019.

# Max Righter Senior Buyer

Interested parties should monitor this website, on a regular basis, for any additional information that may be posted



STATE OF RHODE ISLAND AND PROVIDENCE PLANTATIONS

Department of Administration Division of Purchases One Capitol Hill, 2<sup>nd</sup> Floor Providence, RI 02908 TEL: (401) 574-8100 FAX: (401) 574-8387 TDD: (401) 574-8228 Website: www.ridop.ri.gov

Questions Received

#### Solicitation #7598904

## Exterior and Interior Masonry Repairs at 1951 Smith St., North Providence

1. What is the existing roof materials?

Answer: It's a singly ply TPO/PVC membrane

2. Does the existing roof have a warranty?

### Answer: No

3. Who is the manufacturer of the existing roofing material?

### Answer: Unknown

4. Is the temporary construction wall to be a fire rated assembly?

### Answer: No

5. Can you please provide details for the wall as you would like it built?

Answer: Interior partitions are 18-gauge steel studs with 1/2inch gypsum wall board on either side, with level 4 finish and paint to match current color scheme.

6. Can you please tell us the manufacturer of the raised access flooring?

#### Answer: No

7. Can you please tell us the type of raised access flooring you would like us to provide?

Answer: The Contractor shall try to match what is existing, if an able to match or ascertain make and model. The contractor shall use a hollow steel flooring similar to "pro access floors", the spec is listed at <a href="https://www.computerfloorpros.com/raised-floor-products/raised-access-flooring/#hollow">https://www.computerfloorpros.com/raised-floor-products/raised-access-flooring/#hollow</a>

8. Will the raised access flooring need to be electro-static dissipate (ESD)?

Answer: No as the existing floor does not have this feature

9. What is the spacing on the roof joists so we know how many post shores to provide?

Answer: The existing construction is unknown and will be verified at the time of construction. , however the contractor is to assume that it should be 6 foot on center

10. Can you please show us the extent of detail #3 on drawing S1?

#### Answer: No

11. Where can we place a storage trailer for materials on the site?

Answer: The area determined as the laydown space is located at the rear of the building along the back wall.

12. Are we to remove and save the window lintel for reuse?

Answer: no, a new lintel shall be installed

13. Will existing lintel, if being reused, need to be finished?



STATE OF RHODE ISLAND AND PROVIDENCE PLANTATIONS

Department of Administration Division of Purchases One Capitol Hill, 2<sup>nd</sup> Floor Providence, RI 02908 TEL: (401) 574-8100 FAX: (401) 574-8387 TDD: (401) 574-8228 Website: www.ridop.ri.gov

Answer: See answer # 12, and the interior is to be finished.

14. What is the warranty period for this project

Answer: 1 year

- 1. The interior temporary construction wall is to extend from the concrete floor through the plenum space to the ceiling.
- 2. The interior temporary construction wall is NOT required to be fire rated.
- 3. The interior temporary construction wall shall be sheathed in at minimum one half inch wooden sheet material on either side.
- 4. Owner to remove and disconnect all electrical components from call center stations.
- 5. Pricing to include The contractor is to unassemble and relocate five work stations dividers and desks for the duration of the project and reassemble upon project competition.
- 6. Pricing to include All exposed interior facing masonry to receive 5/8 gypsum wall board over 1.5" wood furring with a level four finish and paint.
- 7. Pricing is to include the removal and storage of Security cameras.
- 8. The raised access floor is not an Electro Static Dissipating assembly.
- 9. The use of a mobile storage device is permissible in the rear area of the building.
- 10. The roof is not under warranty.
- 11. The roof is a single ply TPO / PVC Membrane.

**BID NUMBER: 7598904** 

BID TITLE: Exterior and Interior Masonry Repairs at 1951 Smith St., North Providence

PRE-BID DATE AND TIME: Wednesday August 14th, 2019 10:00 am

COMPANY NAME	COMPANY REPRESENTATIVE	L SIGNATURE	ADDRESS	CONTACT E-MAIL	CONTACT PHONE NUMBER
State of RI Division of Purchases	Max Righter		1 Capitol Hill Providence, RI 02908	max.righter@purchasing.ri.gov 40	401-574-8179
Curt cast meaning	Anis Jasuel	A A	SIS Greenville Ave Thursten	Onnis Decmri, net 401 490-1808	01 490 - 1808
(Dinasany	l .	Warden		Chi used Colores	724-299-1248 Chronecour
Tower construction	MARC B. NOUMAN	MBUM	10 Satthern INOUSTRIAL DR. Crantsrdy, RJ 02921	TOWERCONSTRUCTION CONTRACTION	2 401.943
SPINE BRES. TNC	KRIST MCLAUGHIUN	.[	1.7	iccrist@spinoales u	401 233, 2820
	DAVID ODEH		1223 MINERAL	ODEHND & 72×1771	1221-422
, OCAMIN	Charles le Die	(Mr. / R.L. I	Pice Zer	Medical Contract 4	7151-104
" JCANN	Tono Man Daud	A	(1) Moundances R2) jour then de Rand dog Rand. 241034	purthand Rade dos RS	(Ce/1/2 . www.
0					5
7					
2					
t					
16					
2014-21 Date 6/5/17		** VENDOR: PLEASE SUBMIT A BUSINESS CARD IF AVAILABLE**	= AVAILABLE**		Page 1 of 2